

Sunstrike when Driving





Sun strike, is blinding sunlight that can affect a driver's vision, making it difficult to see the road ahead.

Understanding and mitigating sun strike is crucial for road safety.

Causes of Sun Strike



- **Low Sun Angle:** Occurs during sunrise and sunset when the sun is near the horizon.
- **Reflection:** Sunlight reflecting off surfaces like water, snow, or other vehicles.
- **Cleanliness of Windshield:** A dirty or streaky windshield can exacerbate the effects of sun glare.



Risks Associated with Sun Strike

- **Reduced Visibility:** Difficulty in seeing traffic signals, road signs, and other vehicles.
- **Increased Reaction Time:** Drivers may have slower reaction times due to impaired vision.
- **Higher Accident Rates:** Studies show a higher incidence of accidents during times of low-angle sunlight.



Preventive Measures

- **Use of Sunglasses:** Polarized sunglasses can reduce glare significantly.
- **Clean Windshield:** Regularly clean both the inside and outside of your windshield to prevent streaks and smudges.
- **Sun Visors:** Use the car's sun visors to block direct sunlight.
- **Adjust Speed:** Reduce speed when facing sun glare to allow more reaction time.
- **Plan Your Route:** If possible, choose routes that avoid driving directly into the sun during peak times.



Technological Solutions


Auto-Dimming Rearview Mirrors: Adjust to reduce glare from headlights behind you.

Tinted Windows: Can help reduce the intensity of sunlight entering the car.

Heads-Up Display (HUD): Projects information onto the windshield, allowing drivers to keep their eyes on the road.

Legal Aspects

- **Regulations on Window Tinting:** Ensure compliance with local laws regarding the permissible level of tint on car windows.
- **Liability in Accidents:** Understanding how sun glare might impact fault determination in accidents.



A photograph of a city street during sunset. The sun is low on the horizon, creating a strong golden glow and lens flare that fills the upper half of the image. On the left, a bus stop shelter is visible with a sign for 'Pimlico Station' and a list of bus routes: 2, 36, 185, 436, N2, and N136. A person is walking on the sidewalk near the bus stop. The road is filled with traffic, including several white delivery vans, a dark SUV, and a car. The street is lined with trees and buildings, and the overall atmosphere is warm and hazy.

Conclusion

Awareness: Being aware of the risks and preventive measures can significantly enhance road safety.

Proactive Measures: Simple actions like wearing sunglasses and keeping the windshield clean can make a big difference.